

# Trac-Lok

## Part Numbers:

- 05012831A\$
- 05252512
- 05252496
- 52098778A\$
- 05103017A\$
- 05161549A\$
- 52111420A\$
- 52068450

## Issue Description:

If ordering this part for broken retaining clips for clutch packs and if the broken retaining clips have not damaged the gears or clutch packs in the Trac-Lok, order the following as it applies. For 52068450, 52111420AA, 05161549AA, and 05103017AA order J0994345AB clutch kit and replace the retaining clips with 05183722AA that contains four retaining clips and instructions on how to install. For 52098778A\*, 05012831A\*, 05252512, and 05252496 order 05252506 clutch kit and replace the retaining clips with 05183722AA that contains four retaining clips and instructions on how to install.

---

Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.